## **Risk assessment**

Name of	Work undertaken by Contractors at the Scout Hut	Date of risk	8 <sup>th</sup> February 2021	Name of who	Tris Cocks
Section or		assessment		undertook this	
Activity				risk assessment	
Activity		Date of next	September 2025	TISK USSESSITIETT	
		review			

Hazard Identified? / Risks from it?	Who is at risk?	How are the risks already controlled? What extra controls are needed?	What has changed that needs to be thought about and controlled?
Hazard – something that may cause harm or damage. Risk – the chance of it happening.	Young people, Leaders, Visitors?	Controls – Ways of making the activity safer by removing or reducing the risk from it.  For example - you might use a different piece of equipment or you might change the way the activity is carried out.	Keep <b>checking</b> throughout the activity in case you need to change itor even <b>stop</b> it! This is a great place to add comments which will be used as part of the review.
High Risk Acitivites / un-isolated utilities – Injury and accidents	Contractors	<ul> <li>Contractors to provide a copy of their Risk Assessment and / or Method Statement for any work being undertaken at the scout hut.</li> <li>Contractors are to be made aware of the Isolation points for Gas, Electric &amp; Water</li> <li>Contractors only to work on systems they are certified for – Gas Safe, NICEIC etc.</li> <li>Contractor to register and provide certification for the work they have undertaken</li> </ul>	
Contractors working along – Contractors Potential accident and not being found		<ul> <li>Lone working by Contractors is to be avoided where possible</li> <li>If working alone; the Leader / committee member controlling the work is to regularly check in with the contractor</li> <li>Contractors to inform the Leader / Committee member when work is completed.</li> </ul>	
Accident – Injury whilst alone	Contractors	<ul> <li>All contractors working at the hut are to be aware of where the first aid kit is located</li> <li>Contractors are to be aware of emergency details located by the entrance door</li> <li>Contractors must have mobile phone nearby to call for help should it be required</li> </ul>	

Checked by	Paul Woodward	Checked by Executive	Lesley Dingle
Line Manager	AGSL		Group Chair
	12 <sup>th</sup> May 2021		31th May 2021

## **Version Control**

Date	Version	Changed by	Comments
8 <sup>th</sup> February 2021	1	Tris Cocks	Initial Version
28 August 2023	1.1	Paul Woodward	Reviewed
10 <sup>th</sup> November	1.2	Paul Woodward	Reviewed

Additional information can be found in the Safety Checklist for Leaders and other information at scouts.org.uk/safety



Version 1.2 1 of 1